



ATTENTION – IMPORTANT USER INFORMATION

Rave SX2500 may display audio and/or SCSI warning messages on boot.

NOTE: These warning messages will in no way effect the stability or performance of your system. If the warning messages need to be removed for cosmetic reasons, use the following procedures.

WARNING: *audiots0: The audio AC97 register has timed out.
audiots0: Audio is now disabled.
audiots0: Please reboot to restore audio...*

To remove the audio warning on boot, perform the following procedure at the ok prompt:

```
{ok} setenv auto-boot-on-error? true  
{ok} asr-disable audio "embedded audio not present"
```

The warning will be replaced by an OBP error due to disabling the audio, but the system will not pause while searching for the audio device when a “boot -r” is executed.

WARNING: *Failed to open device (/pci@1e,600000/isa@7/i2c@0,320/gpio@0,30:pca9556_0), rv(6)...*

The following procedure will need to be executed each time the operating system is reloaded. To remove the SCSI warning message, perform the following procedure at the Solaris level:

```
# cd /platform/^uname -i`  
# cd kernel/drv  
# cp ppm.conf ppm.conf.orig  
# vi ppm.conf
```

Comment out the entire blocks of text that reference `.../gpio@0,30....` including the preceding "domain" lines. (CDE Text Editor can also be used to modify the file.)

Save the file and reboot.

If questions arise please contact Rave at 800-966-7283 or support@rave.com.